

NEW

JUMPDOWN JUNCTIONS



AS/NZS 3500.2 Clause 4.9.1.2 was updated such that branch lines coming into the main drain must be installed with at minimum 15° incline to ensure they are higher than the main sanitary line.



Specification Data

ID		A	B			
20966	100	252	297	RH	FxF	9
20967	100	252	297	LH	FxF	9
21169	100	252	297	RH	MxF	9
21170	100	252	297	LH	MxF	9

- Solvent Weld
- 15° Incline
- Heavy Duty Wall Thickness
- Visual Indicators
- Left & Right hand configurations

